ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 7 | Byatarayanapura |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0661 | NA | Amruthalli lake ( Storm Water Drain) |
| **Segment No.** | **Total Length (m)** | |
| 7/S-W0661/S051350 | 157.81 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 157.81 | 77.601442 | 13.060184 | 77.601460 | 13.061610 | Main Road | Dead End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Package No 05 ( Consists of 09 Works) | 45000000 | 2016-17 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2016 - 2017 | Road | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | 1.Desilting of existing drains2.Providing and laying bituminous concrete road3.Providing lane painting | 007-16-000035, 007-16-000036, 007-16-000037, 007-1 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/47/ 2017-18 | 04/01/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 05/02/2018 | 05/02/2020 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| M/s Ram and Company , C.R Girish | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9886110111 | | |



AE(W2)

Assistant Executive Engineer
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.

## ıd Inspection Details

**Number of Trees**

4

**Any Other Information**

**Name**

Pushpalatha.N.D

**Date of Inspection**

14/02/2018

**Remarks**

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition |  | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Parameshwaraiah | 20/02/2018 | 16/03/2018 | Approved |
| SE | Vasu K M | 20/02/2018 | 16/03/2018 | Completed |
| EE | Mohandas H.T | 15/02/2018 | 16/03/2018 | Forwarded |
| AEE | H.Ranganath | 14/02/2018 | 16/03/2018 | Forwarded |
| AE | Mobile Verification Done | 14/02/2018 | 16/03/2018 | Mobile Verification Done |
| AE | Pushpalatha.N.D | 14/02/2018 | 16/03/2018 | Forwarded |

**Zone:** YELAHANKA

**Ward No:** 7

**Ward Name:** Byatarayanapura

**Street ID:** W0661

**Date:** 20/02/2018

Time: 18:08:35

RH 20180220180835



Pushpalatha.N.D
AE(22)

Assistant Executive Engineer
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 7 | Byatarayanapura |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0665 | NA | Amruthalli lake ( Storm Water Drain) |
| **Segment No.** | **Total Length (m)** | |
| 7/S-W0665/S050251 | 160.71 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 160.71 | 77.601810 | 13.060202 | 77.601819 | 13.061654 | High tension Main Road | Dead End |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Package No 05 ( Consists of 09 Works) | 45000000 | 2016-17 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2016 - 2017 | Road | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | 1.Desilting of existing drains2.Providing and laying bituminous concrete road3.Providing lane painting | 007-16-000035, 007-16-000036, 007-16-000037, 007-1 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/47/ 2017-18 | 04/01/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 05/02/2018 | 05/02/2020 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| M/s Ram and Company , C.R Girish | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9886110111 | | |



Assistant Executive Engineer
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,

## ld Inspection Details

**Number of Trees**

3

**Any Other Information**

**Name**

Pushpalatha.N.D

**Date of Inspection**

14/02/2018

**Remarks**

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition |  | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Parameshwariah | 20/02/2018 | 16/03/2018 | approved |
| SE | Vasu K M | 20/02/2018 | 16/03/2018 | Completed |
| EE | Mohandas H.T | 15/02/2018 | 16/03/2018 | Forwarded |
| AEE | H.Ranganath | 14/02/2018 | 16/03/2018 | Forwarded |
| AE | Pushpalatha.N.D | 14/02/2018 | 16/03/2018 | Mobile Verification Done |
| AE | Pushpalatha.N.D | 14/02/2018 | 16/03/2018 | Forwarded |

**Zone:** YELAHANKA

**Ward No:** 7

**Ward Name:** Byatarayanapura

**Street ID:** W0665

**Date:** 20/02/2018

Time: 18:24:42

RH 20180220182442



Assistant Executive Engineer,
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,